Affaires autochtones et Développement du Nord Canada

867-777-2090

http://www.aandc-aadnc.gc.ca

a http://www.aadnc-aandc.gc.ca
Telephone: 867-777-8900

Fax:

P.O. Box 2100 Inuvik, NT X0E 0T0

North Mackenzie District

March 29, 2014

Northwest Territories Water Board P.O. Box 2531 Inuvik, NT X0E 0T0

Attn: Freda Wilson, Office and Finance Administrator

RE: INDUSTRIAL Water Use N7L1-1814

CLASS B - INDUSTRIAL

Johnson Point Unnamed River

Dear Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8909.

Sincerely,

Jan/Davies

Water Resource Officer

Cc: Conrad Baetz, District Manager, North Mackenzie District, Inuvik, NT

Enclosure: Final Industrial Water Use Inspection Report and Cover Letter (4 pages)

Affaires autochtones et Développement du Nord Canada http://www.aadnc-aandc.gc.ca

http://www.aandc-aadnc.gc.ca

North Mackenzie District Telephone: 867-777-8900 P.O. Box 2100 Fax: 867-777-2090

Inuvik, NT X0E 0T0

March 29, 2014

Contaminants & Remediation Directorate Aboriginal Affairs and Northern Development Canada P.O. Box 1500 Yellowknife, NT X1A 2R3

Attn: Bill Coedy

RE: INDUSTRIAL Water Use N7L1-1814

CLASS B - INDUSTRIAL

Johnson Point Unnamed River

Dear Mr. Coedy,

A Final Inspection of the Contaminants & Remediation Directorate - Aboriginal Affairs and Northern Development Canada Water Licence N7L1-1814 (expiry on July 9, 2009) was conducted on August 30, 2013. The operation under the above mentioned Industrial Water Use was inspected to assess compliance and ensure that the terms and conditions were met. Enclosed is a copy of the Inspection Report (3 pages) for your review and records.

There were no violations identified during the course of this Inspection. Please review and address the concerns and other items throughout the Inspection Report.

Please note that it is the Licensee's responsibility to ensure compliance with all of the terms and conditions of its Water Licence. A copy of this report will be sent to the Northwest Territories Water Board for their review and public records.

If you have any questions regarding the enclosed and/or if additional information is required, please do not hesitate to contact me at (867) 777-8900.

Sincerely,

Jan/Davies

Water Resource Officer

Cc: Conrad Baetz, District Manager, North Mackenzie District, Inuvik, NT

Enclosure: Final Industrial Water Use Inspection Report (3 pages)

http://www.aandc-aadnc.gc.ca

INDUSTRIAL WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1814, Johnson Point	EXPIRY DATE:	July 09, 2009
LICENCEE:	Contaminants & Remediation Directorate	PREVIOUS INSPECTION:	New
COMPANY REP:	Bill Coedy	INSPECTION DATE:	August 30, 2013

WATER SUPPLY

Source:	Unnamed River	Quantity Used:	N/A, See Annual Reports
Owner/Operator:	Contaminants & Remediation Directorate	Meter Reading:	N/A

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable N/I - Not Inspected

Intake Facilities	N/A	Storage Structures	N/A	Treatment Systems	N/A	Recycling	N/A
Flow Meas. Device	N/A	Conveyance Lines	N/A	Pumping Stations	N/A	Chem. Storage	N/A
						Modifications	N/A

Water Supply Comments:

N/A

WASTE DISPOSAL – SEWAGE

Disposal Method		grey water sump							
Mechanical	N	Camp Sump	N	Natural Water Body	N	Wetland Treatment	N		
Continuous Discharge	N	Intermittent Discharge	N	Seasonal Discharge	N	Land Spread	N		
Accelerated Biological	N	Other	grey water sump						

 $\label{eq:continuous_problem} \textbf{Indicate:} \qquad \textbf{A - Acceptable} \qquad \textbf{U - Unacceptable} \qquad \textbf{N/A - Not Applicable} \qquad \textbf{N/I - Not Inspected}$

Discharge Quality	N/A	Decent Process & Structures	N/A	Discharge Measurement Device	N/A
Freeboard	N/A	Sludge Disposal Method	N/A		
Periods Of Discharge	N/A			SNP Samples Collected	N/A
Effluent Discharge Rates	N/A				

Sewage Comments:

WASTE DISPOSAL – SOLID WASTE

Disposal Metho	Landfill									
Open Dump	N	Landfill	Y	Burn & Landfill	N	Underground	N			
Offsite Removal	N	Other	Other N/A							
Owner / Operator	Contaminants &	Contaminants & Remediation Directorate								

 $\label{eq:continuous_problem} \textbf{Indicate:} \qquad \textbf{A - Acceptable} \qquad \textbf{U - Unacceptable} \qquad \textbf{N/A - Not Applicable} \qquad \textbf{N/I - Not Inspected}$

	Date:	August 30, 2013	Licence #:	N7L1-1814	Page No:	1
--	-------	-----------------	------------	-----------	----------	---

⁻ Camp areas and surrounding staging areas were in good condition with no concerns. Grey water sump has been removed.

Aboriginal Affairs and

INDUSTRIAL WATER USE INSPECTION REPORT

Runoff Diversion	N/A	SNP Samples Collected	N/A
------------------	-----	-----------------------	-----

Solid Waste Comments:

- Minimal debris waste was observed such as a metal come along on the most southerly treated soil disposal area. It is thought that this might have been from the recent remediation activity (Water Licence N7L1-1824) if not some of the past historic/staging activities associated with Johnson Point. When Contaminants & Remediation Directorate - Aboriginal Affairs and Northern Development is in the area doing monitoring etc any debris exposed on site should be removed for proper disposal.

GENERAL CONDITIONS/REPORTS/PLANS

Indicate:	A - Acceptable	e T	U - Unacceptable	N/A - Not Applic	able N/I - Not Inspected	
C &R Plan		N/A	Records & Reporting	N/I	Final Report	N/A
Geotechnical	Inspection	N/A	Posting, Signage	N/A	Contingency Plan	N/A
Restorations	Activities	A	Spills	A	O&M Plan	N/A
Maintenance		N/A	Modifications	N/A	Annual Report	N/I

General Condition Comments:

Erosion - Acceptable

- Area restoration has been completed. All equipment, camp and materials have been removed from the site. Tank farm area sump has been removed.

NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE

N/A	
Inspector's Signature:	

Date:	August 30, 2013	Licence #:	N7L1-1814	Page No:	2

INDUSTRIAL WATER USE INSPECTION REPORT

Inspection Images:

Figure 1
Aerial view of area north of runway, small lake, and access road.



Area adjacent to small lake and access road.





Figure 3
Along access road and facing southeast towards runway.

Figure 4Area adjacent to runway where access road intersects.





Figure 5 Example of debris (come along) found on site.



Date:	August 30, 2013	Licence #:	N7L1-1814	Page No:	3	l
-------	-----------------	------------	-----------	----------	---	---