



INDIAN AND NORTHERN AFFAIRS - CANADA N.W.T. REGION SEP 28 1999 WATER RESOURCES DIVISION

COPY BOARD, G.W. EA. W. RES. TO 1619

MUNICIPAL WATER USE INSPECTION FORM

DATE: July 27, 1999 COMPANY REP.: LICENCE #: N7L3-1619

WATER SUPPLY

Source (s): NEW WATER LAKE Quantity Used (to date): UNKNOWN
Owner/Operator: HAMLET
Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
Intake Facilities: A Storage Structure N/A Treatment Systems A Chem. Storage A
Flow Meas. Device A Convey. Lines N/A Pumping Stations A
Comments: SAMPLE TAKEN BY INSPECTOR BEFORE TREATMENT. NO PROBLEMS NOTED WITH WATER SUPPLY.

WASTE DISPOSAL

Sewage Sewage Treatment System (primary, secondary or tertiary) PRIMARY
Natural Water body Continuous Discharge (land or water)
Seasonal Discharge NONE N/A OFF Wetlands Treatment TIDE Trench
Solid Waste: Owner/Operator: HAMLET
Landfill Burn & Landfill Other
Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
Disch. Quality A Decant Structure N/A Erosion U
Disch. Meas. Dev. N/A Dyke Inspection N/A Seepages N/A
Dams, Dykes N/A Freeboard A Spills NONE REPORTED.
Construction A - NEW CHARGE CELL O & M Plan U - REVISIONS NOT A & R Plan NO REVISIONS SUBMITTED.
Periods of Discharge: NONE N/A OFF HIGH PRECIPITATION Effluent Discharge Rate: NATURAL OUTFLOW 2.02 L/S NO FACILITIES MAINTAINED.
Comments: NO LEGAL ANIMAL PAT. NO HAZARDOUS MATERIALS TO BE AREA.
OLD GARBAGE CELL FULL - REQUIRES CONSTRUCTION AND COVERING.
NEW GARBAGE CELL DRY. OLD FUTURE CELLS STILL FULL OF WATER.
TIE IN HAS FLOW AT THE SAND HOLE-2 ON HIGHWAY THAT LEAKS INTO THE OCEAN.

FUEL STORAGE

Owner: Operator Condition of Tanks
Berms & Liners Water within berm: Evidence of Leaks:
Drainage Pipes Pump Station and Catchment Berm
Pipeline Condition Not Applicable:

SURVEILLANCE NETWORK PROGRAM

Samples Collected: (Hamlet) NONE. (DIAND) SAMPLES TAKEN AT SNA 1619-1 AND 1619-2 BY INSPECTOR.
Signs Posted: SNP NOT POSTED Warning YES.
Record & Reporting 1997 1998 ANNUAL REPORTS NOT AVAILABLE FROM LICENSEE DUE TO PREVIOUS ADMINISTRATION PRACTICES. 1997 AND 1998 ANNUAL REPORTS WERE RECEIVED FULL BY 1999.
Geotechnical Inspection: N/A

Non-Compliance of Act or Licence:

- VIOLATIONS: 1. PART F, ITEM 1: 1997 AND 1998 ANNUAL REPORTS RECEIVED LATE. 2. PART H, ITEM 1: NO REVISED O+M PLAN FOR WHITE JOURNAL FACILITIES SUBMITTED. 3. PART B, ITEM 5: SNP STATIONS NOT POSTED. 4. SNP, R1: THE LICENSEE HAS NOT SAMPLED SNP 1619-2.

Licencee Representatives Title Licensee Representatives Signature

Inspectors Name Inspectors Signature