



Indian and Northern
Affairs Canada
www.inac.gc.ca

North Mackenzie District
P.O. Box 2100
Inuvik, NT

Affaires Indiennes
et du Nord Canada
www.ainc.gc.ca

Telephone: 867-777-8900
Fax: 867-777-2090

August 17, 2009

Northwest Territories Water Board
P.O. Box 2531
Inuvik, NT X0E 0T0



Attn: **Mike Harlow, Executive Director**

RE: **Industrial Water Use (N7L1-1760)**

Dear Mr. Harlow,

Please find the enclosed Inspection/Audit Report for your review and/or records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

With the exception of the administrative violation as indicated in the Inspection Report, Indian and Northern Affairs Canada (INAC) North Mackenzie District was unable to identify any water use and/or waste disposal issues as a result of this Water Licence. INAC North Mackenzie District **"Recommends File Closure" of Water Licence N7L1-1760**, pending the NWT Water Board's acceptance of the Licensee's compliance with this Water Licence.

If you have any questions/concerns regarding the enclosed/attached, and/or if additional information is required, please do not hesitate to contact me at (867) 777-8909.

Sincerely,

Jan Davies
Water Resource Officer

Cc: Conrad Baetz, District Manager, North Mackenzie District, Inuvik, NT

Enclosure: Industrial Inspection/Audit Report and Cover Letter (3 pages)



Indian and Northern
Affairs Canada
www.inac.gc.ca

North Mackenzie District
P.O. Box 2100
Inuvik, NT, X0E 0T0

Affaires Indiennes
et du Nord Canada
www.ainc.gc.ca

Telephone: 867-777-8900
Fax: 867-777-2090

August 17, 2009

EnCana Corporation
150-9 Avenue S.W.
P.O. Box 2850
Calgary, AB, T2P 2S5

Attn: Craig Temple

RE: Industrial Water Use (N7L1-1760)

Dear Mr. Temple,


A final inspection/audit of the Encana Corporation Water Licence N7L1-1760 (expiry November 30, 2002) was conducted on August 17, 2009. Specifically, the Water Licence was inspected to ensure that the terms and conditions were met. Enclosed is a copy of the Inspection Report (1 page) for your review and/or records.

Unfortunately, there was one violation during this inspection period. Please review this violation on the Inspection Report. Specifically, our records indicate that the requirement under Part B1 relating to the Annual Report submission has not been received by the Northwest Territories Water Board. If this issue has been addressed please contact the undersigned at your earliest convenience.

Indian and Northern Affairs Canada(INAC) North Mackenzie District was unable to identify any water use and/or waste disposal issues as a result of this Water Licence. Please note that final consideration for file closure of a Water Licence is mandated by the NWT Water Board, and pending it's acceptance of your compliance with this Water Licence, INAC North Mackenzie District **"Recommends File Closure"** of Water Licence N7L1-1760.

If you have any questions/concerns regarding the enclosed/attached, and/or if additional information is required, please do not hesitate to contact me at (867) 777-8909.

Sincerely,

A handwritten signature in blue ink, consisting of two large loops followed by a horizontal stroke.

Jan Davies
Water Resource Officer

Cc: Conrad Baetz, District Manager, North Mackenzie District, Inuvik, NT
Inuvik Sub-District

Enclosure: Water Licence Inspection Report (1 page)



INDUSTRIAL WATER USE INSPECTION REPORT

DATE:	August 17, 2009	COMPANY REP:	Craig Temple
LICENCEE:	EnCana Corporation	LICENCE #:	N7L1-1760

WATER SUPPLY

Source:	Mackenzie R and assorted Lakes	Quantity Used:	See Annual Report	Meter Rdg:	N/A
---------	--------------------------------	----------------	-------------------	------------	-----

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable	N/I - Not Inspected			
Intake Facilities	N/A	Storage Structures	N/A	Treatment Systems	N/A	Recycling	N/A
Flow Meas. Device	N/A	Conveyance Lines	N/A	Pumping Stations	N/A	Modifications	N/A

Comments:

No concerns or outstanding issues. Please refer to the February 27, 2001 Inspection Report and 2001 Annual Report.

WASTE DISPOSAL

Well Waste	Off-Site Removal	N/A	Drilling Sump	N/A	Downhole	N/A	Land spread	N/A
Tailings:	Tailings Pond	N/A	Natural Lake	N/A	Under ground	N/A		
Sewage:	Sewage Treat. System	N/A	Tailings pond	N/A	Natural Water Body	N/A		
	Continuous Discharge	N/A	Inter. Discharge	N/A				
Solid Waste:	Open Dump	N/A	Landfill	N/A	Burn & Bury	N/A	Under ground	N/A

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable	N/I - Not Inspected			
Discharge Quality	N/A	Conveyance Lines	N/A	Disch. Meas. Dev.	N/A	Freeboard	N/A
Decant Structures	N/A	Pond Treatment	N/A	Dams, Dykes	N/A	Seepages	N/A
Dyke Inspections	N/A	Runoff Diversion	N/A	Erosion	N/A	Spills	N/A

Effluent Discharge Rate:	N/A	Samples Collected:	N/A
--------------------------	-----	--------------------	-----

Comments:

- Site was acceptable during the February 27, 2001 Water Licence Inspection and subsequent Land Use Inspection/Permit Closure.
- Sewage waste was incinerated and the inert material was transported to Inuvik for disposal at the landfill site. All other solid wastes generated by the camps were also hauled to the Inuvik landfill.

GENERAL CONDITIONS

Indicate:		A - Acceptable	U - Unacceptable	N/A - Not Applicable	N/I - Not Inspected
Ore & Waste Rock Stockpiles	N/A	Records & Reporting	U	Surv. Net. Prog.	N/A
Geotechnical Inspection	N/A	Posting, Signage	N/A	Contingency Plan	N/A
Restorations Activities	N/A	New Construction	N/A	Fuel Storage	N/A
Mine Water Discharge	N/A	Chemical Storage	N/A	Annual Report	U