



April 17, 2015

Terence Hughes  
Regulatory and Community Affairs Advisor  
MGM Energy  
#4700, 888 – 3rd Street SW  
Calgary, AB T2P 5C5

Dear Mr. Hughes:

**Re: Water Licence N7L1-1797 MGM Energy Corp., Burnt Lake Drilling – 2014 Annual Sump Environmental Inspection Report**

The Inuvialuit Water Board (IWB) acknowledges receipt of the above mentioned annual report submitted by the MGM Energy along with a cover letter dated February 23, 2015. Upon review of the report, information gaps were noted as required by *Part H: Conditions Applying to Abandonment and Restoration* of the Water Licence. To address these information gaps please provide the following:

1. As required by Part H, Item 2a, provide Thermistor Measurements Data including Temperature Graphs and Summary Tables.
2. In accordance with Part H, Item 2b, please provide the observations of the salinity migration obtained by using electromagnetic induction.

The submitted report including the IWB response will be placed on the IWB Public Register.

Should you have any questions, please do not hesitate to contact me at 867-678-8610 or email: [adhikarib@nwtwb.com](mailto:adhikarib@nwtwb.com) or Mardy Semmler, Executive Director, at 867-678-8609 or email: [semmlerm@nwtwb.com](mailto:semmlerm@nwtwb.com).

Sincerely,

Dr. Bijaya Adhikari  
Science and Regulatory Coordinator

cc: Philippe Thibert-Leduc, Water Resources Officer, ENR Inuvik