



May 11, 2015

Inuvialuit Water Board
PO Box 2531
Inuvik, NT
XOE 0T0

Ms. Mardy Semmler
Executive Director

Dear Ms. Semmler:

Unipkat I-22
Inuvialuit Water Board response comments for the 2014 Monitoring and Maintenance
Program Summary Report

Thank you for your feedback regarding the Unipkat I-22 2014 Monitoring and Maintenance Program Summary Report. This report was unfortunately issued to the Inuvialuit Water Board (IWB) in error. It is our understanding reports were to be submitted to the IWB for the duration of the Industrial Water License (N7L1-1831), which expired September 30, 2013. We apologize for this oversight.

Regardless, we appreciate your comments and have addressed points (1) and (2) outlined in the IWB response letter. Also requested in the IWB response letter were mitigative measures to address earth cracking. Shell Canada Energy (Shell), Tervita Corporation (Tervita), IEG Consultants Ltd. (IEG), and Aboriginal Affairs and Northern Development Canada (AANDC) have engaged in prior discussions regarding this matter and the applicable mitigative measures appropriate for the region. Currently the manual filling of cracks is agreed to be most appropriate. Shell, Tervita, IEG, and AANDC will continue to work together on this important issue and adjust mitigations as needed.

If you have any further questions or comments, please don't hesitate to contact me at (403) 730-6809 or nwills@klohn.com.

Yours truly,
IEG CONSULTANTS LTD.

Nicole Wills, P.Ag.
Project Manager

NW

c.c.: Randall Warren – Shell Canada Energy

150511P IWB Response