

Terrence Hughes
Regulatory and Community Affairs Advisor
MGM Energy Corp.
#2800, 421 – 7<sup>th</sup> Avenue SW
Calgary, AB T2P 4K9

July 29, 2020

Attention:

**Terrence Hughes** 

File Number

N7L1 - 1797

Type of Operation

**CLASS B - INDUSTRIAL** 

Location

**Burnt Lake** 

A final inspection of the above noted operation was conducted by Water Resource Officer Lloyd Gruben, on July 21, 2020.

Weather during the inspection was cloudy, scattered showers, fog patches, +10 degrees celcius.

During the inspection, we observed possible leaching, dead vegetation. This was also noted in my inspection report dated: August 14, 2017. With the concerns we observed during the inspection, a re - assessment will be required of the sump. I also requested this in my August 14, 2017 inspection report.

Enclosed is a copy of the INDUSTRIAL Water Use Inspection Report.

If you have any questions or concerns regarding this inspection report, please contact at the phone numbers provided below.

Sincerely,

Lloyd Gruben

Water Resource Officer

Dept. of ENR

P.O. Box 2749

Inuvik, NT X0E 0T0

867 678 6676 (office)

867 - 678 - 0623 (cell)



Cc:

Norman Snowshoe

Superintendent, Dept of ENR

Mardy Semmler

Executive Director, Inuvialuit Water Board

Bijaya Adkihara

Science and Regulatory Coordinator, Inuvialuit Water Board



LICENCE #:	N7L1 - 1797	EXPIRY DATE:	December 31, 2008
LICENCEE:	MGM Energy Corp.	PREVIOUS INSPECTION:	August 2, 2017
COMPANY REP:	Terrence Hughes	INSPECTION DATE:	July 21, 2020

### **WATER SUPPLY**

Source:	Source: N/A C		N/A
Owner/Operator:	N/A	Meter Reading:	N/A

Indicate:

A - Acceptable

U - Unacceptable N/A - Not Applicable N/I - Not Inspected

Intake Facilities	N/A	Storage Structures	N/A	Treatment Systems	N/A	Recycling	N/A
Flow Meas. Device	N/A	Conveyance Lines	N/A	Pumping Stations	N/A	Chem. Storage	N/A
						Modifications	N/A

### **Water Supply Comments:**

No Comment

### WASTE DISPOSAL - SEWAGE

Disposal Met	hod	N/A					
Mechanical	N/A	Camp Sump	N/A	Natural Water Body	N/A	Wetland Treatment	N/A
Continuous Discharge	N/A	Intermittent Discharge	N/A	Seasonal Discharge	N/A	Land Spread	N/A
Accelerated Biological	N/A	Other	N/A				

Indicate:

A - Acceptable

U - Unacceptable

N/A - Not Applicable N/I - Not Inspected

Discharge	N/A	Decant Process &	N/A	Discharge	N/A
Quality		Structures		Measurement Device	
Freeboard	N/A	Sludge Disposal Method	N/A		N/A
Periods Of	N/A			SNP Samples Collected	N/A
Discharge					,
Effluent	N/A				
Discharge	**				
Rates					

Date:	Licence #:	Page No: 1



## **Sewage Comments:**

No Comment

### WASTE DISPOSAL - SOLID WASTE

Disposal M	ethod	N/A					
Open Dump	N/A	Landfill	N/A	Burn & Landfill	N/ A	Underground	N/A
Offsite Removal	N/A	Other	N/A				
Owner / Operator	N/A	1	I				

Indicate:

A - Acceptable

U - Unacceptable

N/A - Not Applicable N/I - Not Inspected

Runoff Diversion N/A	SNP Samples Collected	No	
----------------------	-----------------------	----	--

#### **Solid Waste Comments:**

No Comment

#### **FUEL STORAGE**

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable	N/I - Not Inspected
		St.	SCOVERUS COST CONTRACTOR NUMBER OF STATE OF STAT	

Owner:	N/A	Operator:	N/A	Condition of tanks:	N/A	
Berms & Liners	N/A	Water within Berm:	N/A	Evidence of Leaks:	N/A	

Drainage Pipes	N/A	Pump Station and Catchment Berm	N/A	Runoff Diversion	N/A
Pipeline Condition	N/A				,

#### **Fuel Storage Comments:**

No Comment

## SURVEILLANCE NETWORK PROGRAM

Samples Collected Licencee	No
Samples Collected ENR	No

Date:	Licence #:	Page No:	2





Signs Posted: SNP N/A	Warning N/A
-----------------------	-------------

### **Surveillance Network Program Comments:**

No Comment

#### **GENERAL CONDITIONS/REPORTS/PLANS**

Indicate:

A - Acceptable

U - Unacceptable

N/A - Not Applicable N/I - Not Inspected

C &R Plan	N/A	Records & Reporting	N/A	Final Report	N/A
Geotechnical Inspection	N/A	Posting, Signage	N/A	Contingency Plan	N/A
Restorations Activities	N/A	Spills	N/A	O&M Plan	N/A
Maintenance	N/A	Modifications	N/A	Annual Report	N/A

#### **General Condition Comments:**

#### **ADDITIONAL COMMENTS/REMARKS**

With the concern of possible leaching, dead vegetation, I, Lloyd Gruben, Water Resource Officer, recommends to the Inuvialuit Water Board that Water License: N7L1-1797 will not be closed as a reassessment is required. This concern was also noted in the August 14, 2017 Inspection report

Licence #:

#### **MATTERS FOR FOLLOW UP**

Re – assessment is required for this sump before the water license is closed.

### **NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE**

Inspector's Signature:

Date:

LD.		
1) Vena	pr-	

Page No:



## **INSPECTION IMAGES**



Figure 1 Has good cover, vegetated, July 21, 2020, N7L1 – 1797 Burnt Lake



Figure 2 Sheen of hydro carbons visible, also dead vegetation, July 21, 2020 N7L1 – 1797 Burnt Lake

Date: Licence #: Page No: 4	Date:	Licence #:	Page No: 4
-----------------------------	-------	------------	------------





Figure 3 Hydro Carbon Sheen visible along with dead vegetation, July 21, 2020, Burnt Lake



Figure 4 Hydro Carbon Sheen, dead vegetation and foam, July 21, 2020, Burnt Lake, N7L1 - 1797

Date:	Licence #:	Page No:	5
_ Milabertersm.	Licence II.	lage No.	2





Figure 5 Hydro carbon sheen, dead vegetation and foam side of sump, N7L1 – 1797, July 21, 2020, Burnt Lake

Date:	Licence #:	Page No:	6