



May 3, 2016

Terence Hughes  
Regulatory and Community Affairs Advisor  
MGM Energy Corporation  
#4700, 888 – 3rd Street SW  
Calgary, AB T2P 5C5

Dear Mr. Hughes:

**Re: N7L1-1802 MGM Energy Corp - Umiak N05 Drilling Sump  
N7L1-1797 MGM Energy Corp - Burnt Lake N16 Drilling Sump and  
N7L1-1787 Chevron Canada Limited - Langley K30 Drilling Sump  
– 2015 Environmental Site Monitoring Reports**

The Inuvialuit Water Board (IWB) acknowledges receipt of the above mentioned annual reports submitted on March 18, 2016. The IWB has completed a review of the submitted reports and as a result of the review, additional information is required:

- N7L1-1802 - As required by Part H, Item 2b) monitor for salinity migration using electromagnetic induction; this information is not provided;
- N7L1-1797 - As required by Part H, Item 2b) monitor for salinity migration using electromagnetic induction; this information is not provided; and
- N7L1-1787 - As required by Part H, Item 2b) monitor for salinity migration using electromagnetic induction; this information is not provided.

Should you have any questions or concerns, contact me at 867-678-8610 or [adhikarib@inuvwb.ca](mailto:adhikarib@inuvwb.ca) or Mardy Semmler, Executive Director, at 867-678-8609 or [semmlerm@inuvwb.ca](mailto:semmlerm@inuvwb.ca).

Sincerely,

Bijaya Adhikari, PhD  
Science and Regulatory Coordinator

cc: Philippe Thibert-Leduc, Water Resources Officer - ENR Inuvik