



MUNICIPAL WATER USE INSPECTION FORM



DATE: JUNE 3, 1997 COMPANY REP.: KEN THOMPSON
 LICENSEE: HAMLET OF PAULATUK LICENCE #: N7L3-1619

WATER SUPPLY

Source (s): NEW WATER LAKE Quantity Used (to date): UNKNOWN
 Owner/Operator: HAMLET (estimate or actual)

Indicate: **A - Acceptable U - Unacceptable N/A - Not Applicable**

Intake Facilities: A Storage Structure N/A Treatment Systems A Chem. Storage A
 Flow Meas. Device A Convey. Lines N/A Pumping Stations A

Comments: SAMPLES TAKEN AT SNP 1619-1.
NO SNP SIGN (SNP 1619-1).

WASTE DISPOSAL

Sewage Sewage Treatment System (primary, secondary or tertiary) PRIMARY
 Natural Water body X Continuous Discharge (land or water) _____

Seasonal Discharge POSSIBLE PEAK RUN-OFF Wetlands Treatment SOME AT OUTFLOW Trench _____
≈ 100m ditch.

Solid Waste: Owner/Operator: HAMLET
 Landfill X Burn & Landfill _____ Other _____

Indicate: **A - Acceptable U - Unacceptable N/A - Not Applicable**

Disch. Quality N/A Decant Structure N/A Erosion N/A
 Disch. Meas. Dev. N/A Dyke Inspection N/A Seepages N/A
 Dams, Dykes N/A Freeboard A Spills NONE REPORTED
 Construction U - new cell contains water O & M Plan U - REVISION NOT SUBMITTED A & R Plan NO REVISIONS SUBMITTED TO DATE.
 Periods of Discharge: REF. SPRING RUN-OFF Effluent Discharge Rate: NATURAL OUTFLOW - ≈ 0.2 m³/s

Comments: SOLID WASTE CELL FULL - requires compaction/burning.
SEWAGE LAGOON COVERED WITH ICE - DIFFICULT TO OUTFLOW - NO SAMPLES TAKEN AT SNP 1619-2.

NUMEROUS BRAIDED STREAMS AT OUTFLOW OF LAGOON. HAMLET WAS REMINDED TO SAMPLE WEEKLY DURING FLOW.

FUEL STORAGE

Owner: JAMES RUPEN CONTRACTOR Operator _____ Condition of Tanks _____
 Berms & Liners N/A Water within berm: _____ Evidence of Leaks: _____
 Drainage Pipes N/A Pump Station and Catchment Berm _____
 Pipeline Condition _____ Not Applicable: _____

COPY	
BOARD.	<u>5</u>
G.W.	<u>1</u>
E.A.	<u>1</u>
W. RES.	<u>1</u>
File -	<u>1619</u>

SURVEILLANCE NETWORK PROGRAM

Samples Collected: (Hamlet) NONE.
 (DIAND) YES. SNP 1619-1 AND SNP 1619-2
 Signs Posted: SNP NO SNP SIGNS. Warning YES
 Record & Reporting UNACCEPTABLE - 1995 + 1996 ANNUAL REPORTS NOT SUBMITTED.

Geotechnical Inspection: N/A

Non-Compliance of Act or Licence: VIOLATIONS: 1. PART B, Item 1: NO 1995 AND 1996 ANNUAL REPORTS SUBMITTED.
2. PART H, Item 1: NO O&M PLAN (REVISED) FOR WASTE FACILITIES SUBMITTED.
3. PART B, Item 5: NO SNP SIGNS. Page 2 attached Yes _____ No X

Ken Thompson
 Licensee Representatives Title
Ken Thompson
 Licensee Representatives Signature

SCOT GALLUPE
 Inspector's Name
[Signature]
 Inspector's Signature



Indian and Northern Affairs Canada

Affaires indiennes et du Nord Canada

Hamlet of Paulatuk

INDIAN AND NORTHERN AFFAIRS - C. W.T. RES. 51

SEP 08 1997

WATER RESOURCES DIVISION YELLOWKNIFE, NT

MUNICIPAL WATER USE INSPECTION FORM

DATE: COMPANY REP: Ken Thompson

LICENSEE: LICENCE #: 1619-
WB
MACT

WATER SUPPLY

Source (s): Quantity Used (to date):
(estimate or actual)

Owner/Operator:

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Intake Facilities: Storage Structure Treatment Systems Chem. Storage

Flow Meas. Device Convey. Lines Pumping Stations

Comments:

WASTE DISPOSAL

Sewage Sewage Treatment System (primary, secondary or tertiary)

Natural Water body X Continuous Discharge (land or water)

Seasonal Discharge Wetlands Treatment Trench

lid Waste: Owner/Operator:

Landfill X Burn & Landfill Other

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Disch. Quality N/A Decant Structure V/A Erosion N/A

Disch. Meas. Dev. N/A Dyke Inspection N/A Seepages N/A

Dams, Dykes N/A Freeboard Spills

Construction A O & M Plan A & R Plan

Periods of Discharge: Effluent Discharge Rate: N/A

Comments:

FUEL STORAGE

Owner: Operator Condition of Tanks

Berms & Liners Water within berm: Evidence of Leaks:

Drainage Pipes Pump Station and Catchment Berm

Pipeline Condition Not Applicable:

SURVEILLANCE NETWORK PROGRAM

amples Collected: (Hamlet)


(DIAND)

Signs Posted: SNP Warning

Record & Reporting

Geotechnical Inspection:

Non-Compliance of Act or Licence:



Page 2 attached Yes No X


Licensee Representatives Title

Licensee Representatives Signature

Inspectors Name

 SCOTT GALLUPE

Inspectors Signature



1619 Water Board
JUL 07 1997
WATER RESOURCES DIVISION
YELLOWKNIFE, N.W.T.

MUNICIPAL WATER USE INSPECTION FORM

DATE: JULY 07 1997 COMPANY REP.: V. J. THOMPSON
LICENSEE: HAMLET OF HAMLET LICENCE #: N7L3-1619

WATER SUPPLY

Source (s): NEW WATER LAKE Quantity Used (to date): UNKNOWN
Owner/Operator: HAMLET (estimate or actual)

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
Intake Facilities: A Storage Structure N/A Treatment Systems A Chem. Storage A
Flow Meas. Device A Convey. Lines N/A Pumping Stations A

Comments: SAMPLES TAKEN AT SNP 1619-1.
NO SUP AT SNP 1619-1.

WASTE DISPOSAL

Sewage Treatment System (primary, secondary or tertiary) PRIMARY
Natural Water body X Continuous Discharge (land or water) _____
Seasonal Discharge _____ Wetlands Treatment NO Trench _____
Owner/Operator: HAMLET
Landfill X Burn & Landfill _____ Other _____

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable
Disch. Quality N/A Decant Structure N/A Erosion N/A
Disch. Meas. Dev. N/A Dyke Inspection N/A Seepages N/A
Dams, Dykes N/A Freeboard A Spills NONE REPORTED
Construction U - new cell contains water O & M Plan U - REVISION NOT GRANTED A & R Plan NO REVISIONS SUBMITTED TO DATE

Periods of Discharge: NO SPRING RUN OFF Effluent Discharge Rate: NATURAL OUTFLOW - 0.2 m³/s
Comments: SOLID WASTE CELL FULL - requires compacting/mulching.
SEWAGE LAGOON (UNDER) WITH ICE - NO OUTFLOW - NO SAMPLES TAKEN AT SNP 1619-2.

NUMEROUS BRAIDED STREAMS AT OUTFLOW OF LAGOON. HAMLET WAS REMINDED TO SAMPLE WEEKLY DURING FLOW.

FUEL STORAGE

Owner: N/A Operator: _____ Condition of Tanks _____
Berms & Liners N/A Water within berm: _____ Evidence of Leaks: _____
Drainage Pipes N/A Pump Station and Catchment Berm _____
Pipeline Condition N/A Not Applicable: _____

SURVEILLANCE NETWORK PROGRAM

Samples Collected: (Hamlet) NONE
(DIAND) SNP 1619-1 AND SNP 1619-2
Signs Posted: SNP NO Warning _____
Record & Reporting NO REPORTS SUBMITTED

COPY	
BOARD.	<u>2</u>
G.W.	<u>1</u>
ENV.	<u>1</u>
W. RES.	<u>1</u>
File #	<u>1619</u>

Geotechnical Inspection: N/A

Non-Compliance of Act or Licence: VIOLATION OF PART 2 HEALTH: NO 1995 AND ONE ANNUAL REPORT SUBMITTED.
VIOLATION OF PART 2 HEALTH: NO 1995 AND ONE ANNUAL REPORT SUBMITTED.

Page 2 attached Yes _____ No X

Licensee Representatives Title
Ken Thompson
Licensee Representatives Signature

Inspectors Name
Scott MacLennan
Inspectors Signature