



INDUSTRIAL WATER USE INSPECTION REPORT
(OIL AND GAS EXPLORATION, PRODUCTION, PROCESSING AND REFINING)

DATE:	APRIL 10, 2002.	COMPANY REP:	DELONA BUTCHER / KIM HARTZUEL
LICENSEE:	CHEVRON CANADA RESOURCES EILICE, MAKLIK AND NORTH LAWLEY SEISMIC PROGRAM.	LICENCE NUMBER:	N7L1-1772

WATER SUPPLY:

Source:	TUKTOYAKTUK MUNICIPAL SUPPLY AND MACKENZIE RIVER CHANNELS.	Quantity Used:	REFER TO RECORDS.	Meter Rdg:	BY TRUCKLOAD.
---------	--	----------------	-------------------	------------	---------------

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable	N/I - Not Inspected			
Intake Facilities	N/I	Storage Structures	N/A	Treatment Systems	N/A	Recycling	N/A
Flow Meas. Device	A	Conveyance Lines		Pumping Stations	A	Modifications	N/A

Comments: THE LICENSEE IS USING TWO DELTA 3'S FOR WATERING ACCESS. THE INSPECTOR WAS TOLD BOTH DELTA 3 HAVE INTAKE SCREENS. THE LICENSEE IS ALSO USING TUK MUNICIPAL WATER FOR CAMP. THE LICENSEE HAS USED A WATER HAULER CONTRACTOR FROM BOTH AKLAVIK AND TUKTOYAKTUK.
SEISMIC PROGRAM.

WASTE DISPOSAL:

Well Wastes:	Drilling Sump	N/A	Off-Site Removal	N/A	Downhole	N/A	Landsread	N/A
Sewage:	Sewage Treat.	N/A	Camp Sump	N/A	Natural Water Body	N/A	Wetlands Treat.	N/A
	Continuous	N/A	Inter. Discharge	TRUCKED PUMPOUT TO TUK SEWAGE LAGOON.				
Solid Waste:	Open Dump	N/A	Landfill	N/A	Burn & Bury	A	Sludge Disposal	N/A

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable	N/I - Not Inspected			
Discharge Quality	UNKNOWN	Conveyance Lines	N/A	Disch. Meas. Dev.	A	Freeboard	N/A
Decant Process	N/A	Sump Treatment	N/A	Dykes, Berms	N/A	Seepages	N/A
Sump Liners	N/A	Runoff Diversion	N/A	Erosion	N/A	Spills	NUMEROUS SMALL SPILLS.

Effluent Discharge Rate:	TRUCK PUMP.	SNP Samples Collected:	N/A.
--------------------------	-------------	------------------------	------

Comments: THE LICENSEE HAD MODIFIED THEIR WASTEWATER DISPOSAL METHOD FROM GREYWATER SEWER STEAMER/INCINERATOR TO TRUCK PUMPOUT AND HAULIED TO TUK SEWAGE LAGOON. THE LICENSEE DID THIS MODIFICATION WITHOUT PROPER NOTIFICATION. THERE WAS SOME GREYWATER SPILLAGE AT CAMPSITE.

GENERAL CONDITIONS:

Indicate:	A - Acceptable	U - Unacceptable	N/A - Not Applicable	N/I - Not Inspected	
Maintenance	A	Records & Reporting	U	Surveillance Network Program (SNP)	N/A
Geotechnical Inspection	N/A	Posting of Facilities	N/A	Contingency Plan	UNDER REVIEW.
A & R Plan	N/A	Modifications	LI	Fuel/Product Storage	A
Groundwater Discharge	N/A	Chemical Storage	N/A	2001 Annual Report	DUE MARCH 31, 2002.

Comments: THERE WERE APPROXIMATELY 60 PEOPLE IN CAMP AT TIME OF THIS INSPECTION. THE LICENSEE HAD APPROXIMATELY TWO DAYS LEFT OF RECORDING OF THE PROGRAM.

Violation(s) of Act and/or Licence: VIOLATIONS: 1. PART B, ITEM 1; NO 2001 ANNUAL REPORT SUBMITTED.
2. PART E, ITEM 1; THE LICENSEE MODIFIED THEIR WASTEWATER DISPOSAL METHOD WITHOUT PROPER NOTIFICATION.

General Comments: ONE WATER TRUCK AT CAMP SITE HAD A SPILL TRAY UNDERNEATH IT AND WAS SPILLING RED TRANSMISSION FLUID.

THE LICENSEE WAS REMINDED TO COMPLY WITH ALL LICENCE TERMS AND CONDITIONS AS SOON AS POSSIBLE.
THE LICENSEE WAS ALSO REMINDED THAT THEIR 2002 ANNUAL REPORT IS DUE MARCH 31, 2003.

Additional Comments Attached:	Yes	No	X
-------------------------------	-----	----	---

Inspector's Signature: [Signature]
Licensee Representative's Title: LAND REPRESENTATIVE / PARTY MANAGER.

Inspector's Title: WATER RESOURCES OFFICER
Licensee Representative's Signature: NOT AVAILABLE.