



Beaufort Delta Region  
Bag Service #1  
Inuvik, NT X0E 0T0

Telephone: 867 777-8900  
Fax: 867-777-2090

August 5, 2014

Inuvialuit Water Board  
P.O. Box 2531  
Inuvik, NT X0E 0T0

**Attn: Freda Wilson, Office and Finance Administrator**

**RE: INDUSTRIAL Water Use N7L1-1797  
CLASS B – INDUSTRIAL  
Umiak/Burnt Lake N16**

To: Ms. Wilson,

Please find the enclosed Inspection Report for your review and records.

An electronic copy (un-editable Adobe pdf.) has also been provided by e-mail.

If you have any questions or concerns regarding the enclosed, and/or if additional information is required please contact me at (867) 777-8900.

Regards,

A handwritten signature in black ink, appearing to read "Arey", written over a light blue horizontal line.

Donald Arey  
Manager Resource Management  
Department of Lands  
Beaufort Delta Region-Inuvik

Cc:

Conrad Baetz, Superintendent, Dept. of Lands, Beaufort Delta Region  
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



Beaufort Delta Region  
Bag Service #1  
Inuvik, NT X0E 0T0

Telephone: 867 777-8900  
Fax: 867-777-2090

August 5, 2014

MGM Energy Corp.  
4700, 888-3rd Street SW  
Calgary, AB T2P 5C5

**Attn:** Terence Hughes

**RE: INDUSTRIAL Water Use N7L1-1797  
CLASS A - INDUSTRIAL  
Burnt Lake Sump**

**To:** Terence Hughes,

An inspection of the above noted operation was conducted on July 31, 2014 by Manager Resource Management Donald Arey.

Enclosed is a copy of the Industrial Water Use Inspection Report.

If you have any questions, please contact me at 867 777-8900.

Regards,

A handwritten signature in black ink, appearing to read "D. Arey", written in a cursive style.

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

Cc:

Conrad Baetz, Superintendent, Dept. of Lands, Beaufort Delta Region  
Stephen Charlie, Superintendent, Dept. of Environment and Natural Resources



## «INSP\_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1-1797	EXPIRY DATE:	December 31, 2014
LICENCEE:	MGM Energy Corp.	PREVIOUS INSPECTION:	August 26, 2013
COMPANY REP:	Terence Hughes	INSPECTION DATE:	July 31, 2014

### WATER SUPPLY

Source:	Mackenzie River/Various Lakes	Quantity Used:	N/A See annual Report
Owner/Operator:	MGM Energy Corp.	Meter Reading:	N/A

**Indicate:**      **A - Acceptable**              **U - Unacceptable**              **N/A - Not Applicable**              **N/I - Not Inspected**

Intake Facilities	N/A	Storage Structures	N/A	Treatment Systems	N/A	Recycling	N/A
Flow Meas. Device	N/A	Conveyance Lines	N/A	Pumping Stations	N/A	Chem. Storage	N/A
						Modifications	N/A

**Water Supply Comments:**

N/A

### WASTE DISPOSAL – WELL WASTE

Disposal Method		Drilling Sump							
Off-Site Removal	N	Drilling Sump	Y	Downhole Injection	N	Treat and Landsread	N	Other	N/A

**Indicate:**      **A - Acceptable**              **U - Unacceptable**              **N/A - Not Applicable**              **N/I - Not Inspected**

Sump Liners	N/A	Sump Treatment	N/A	Freeboard	N/A
Erosion	N/A	Construction	N/A		
SNP Samples Collected	N/A				

**Well Waste Comments:**

The sump has a good slope for drainage. As per previous inspection report for August 26 2013, There is some water presence in some polygons by the sump and this should continued to be monitored to ensure the sumps stability/integrity.

### WASTE DISPOSAL – SOLID WASTE

Disposal Method		Landfill							
Open Dump	N	Landfill	Y	Burn & Landfill	N	Underground	N		
Offsite Removal	N	Other	N/A						
Owner / Operator	MGM Energy Corp.								

**Indicate:**      **A - Acceptable**              **U - Unacceptable**              **N/A - Not Applicable**              **N/I - Not Inspected**



# «INSP\_TYPE» WATER USE INSPECTION REPORT

Runoff Diversion	N/A	SNP Samples Collected	N/A
------------------	-----	-----------------------	-----

**Solid Waste Comments:**

As per previous comments on Waste Disposal

**GENERAL CONDITIONS/REPORTS/PLANS**

Indicate:      A - Acceptable              U - Unacceptable              N/A - Not Applicable              N/I - Not Inspected

C &R Plan	N/A	Records & Reporting	N/I	Final Report	N/A
Geotechnical Inspection	N/A	Posting, Signage	N/A	Contingency Plan	N/A
Restorations Activities	A	Spills	N/A	O&M Plan	N/A
Maintenance	N/A	Modifications	N/A	Annual Report	N/I

**General Condition Comments:**

-Thermistors on site. -Good vegetation. -Water presence in the polygons to the SW and the NE of the sump.

Inspector's Signature:



## «INSP\_TYPE» WATER USE INSPECTION REPORT

Inspection Images:

**Figure 1**

**Water in the polygons SW of sump**

---



**Figure 2**

**Water in the polygons NE of sump**

---



**Figure 3**  
**Good Veg. Cover**



**Figure 4**  
**Looking North**

