



Telephone: 867-678-6676
Fax: 867-678-6699

September 17, 2018

Chevron Canada Resources
500 - fifth Avenue SW
Calgary, AB T2P 0L7

Attention: Sheldon Scyrup

File Number N7L1 - 1772
Type of Operation CLASS B - CAMPS (> 50 MAN)
Location Type B

Dear Sheldon Scyrup,

An inspection of the above noted operation was conducted on September 13, 2018 by Water Resources Officer Lloyd Gruben .

Enclosed is a copy of the INDUSTRIAL Water Use Inspection Report.

If you have any questions, please contact me at 867-678-6676.

Sincerely,

Lloyd Gruben
Water Resources Officer
Environment and Natural Resources
Beaufort Delta

Cc:

Norman Snowshoe - Regional Superintendent, Dept of ENR, Beaufort Region

Mardy Semmler - Executive Director, Inuvialuit Water Board



«INSP_TYPE» WATER USE INSPECTION REPORT

Bijaya Adkihara - Science and Regulatory Coordinator – Inuvialuit Water Board

Freda Wilson - Inuvialuit Water Board



«INSP_TYPE» WATER USE INSPECTION REPORT

LICENCE #:	N7L1 - 1772	EXPIRY DATE:	December 31, 2002
LICENCEE:	Chevron Canada Resources	PREVIOUS INSPECTION:	New
COMPANY REP:	Sheldon Scyrup	INSPECTION DATE:	September 13, 2018

WATER SUPPLY

Source:	Type B	Quantity Used:	
Owner/Operator:	Chevron Canada Resources	Meter Reading:	

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Intake Facilities	N/I	Storage Structures	N/I	Treatment Systems	N/I	Recycling	N/I
Flow Meas. Device	N/I	Conveyance Lines	N/I	Pumping Stations	N/I	Chem. Storage	N/I
						Modifications	N/I

Water Supply Comments:

No Activity

WASTE DISPOSAL - WELL WASTE

Disposal Method									
Off-Site Removal	N	Drilling Sump	N	Downhole Injection	N	Treat and Lands prepared	N	Other	

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

Sump Liners	N/I	Sump Treatment	N/I	Freeboard	N/I
Erosion		Construction	A		
SNP Samples Collected	none				



«INSP_TYPE» WATER USE INSPECTION REPORT

Well Waste Comments:

No Activity

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan	N/A	Records & Reporting	N/A	Final Report	N/A
Geotechnical Inspection	N/A	Posting, Signage	N/A	Contingency Plan	N/A
Restorations Activities		Spills	N/A	O&M Plan	N/A
Maintenance	N/A	Modifications	N/A	Annual Report	N/A

General Condition Comments:

No Activity

ADDITIONAL COMMENTS/REMARKS

Final inspection was done at both sites of Water License N7L1 - 1772. Ellice/North Langley Camp no issues or concerns.

Final Inspection done for Water License N7L1 - 1772 Mallik Camp. The camp sump was flooded with water, no oily sheen noticed. Water was clean and clear. Had no issues or concerns.



«INSP_TYPE» WATER USE INSPECTION REPORT

With this final inspection of Water License N7L1 - 1772, I recommend that this water be considered closed and security deposit be returned

Inspector's Signature:  _____



«INSP_TYPE» WATER USE INSPECTION REPORT

INSPECTION IMAGES

Figure 1



Figure 2



Figure 3

