



Aboriginal Affairs and  
Northern Development Canada

Affaires autochtones et  
Développement du Nord Canada

P.O. Box 1500  
4923 52<sup>nd</sup> Street  
Yellowknife, NT  
X1A 2R3

July 30<sup>th</sup> 2015

Aboriginal Affairs and Northern Development Canada – CARD  
P.O. Box 1500  
4923 52<sup>nd</sup> Street  
Yellowknife, NT  
X1A 2R3

Attention: Ms. Emma Pike, AANDC CARD

**RE: Type B Water Licence N7L1-1814 & N7L1-1824 – Johnson Point Remediation Project – Johnson Point, NT – Inspection**

Dear Ms. Pike,

An inspection of both Johnson Point water licences was completed by Resource Management Officer Tim Morton on July 10<sup>th</sup> 2015. The inspection was conducted to ensure compliance with the terms and conditions of both water licences N7L1 – 1814 and N7L1-1824.

There were no concerns noted during the inspection with any aspect of the site. There was no identified water use or waste disposal associated with either of the water licences issued to Aboriginal Affairs and Northern Development Canada – CARD. Therefore AANDC Resources and Lands Inspector **recommends closure of both water licences N7L1-1814 and N7L1-1824** to the NWT Water Board.

A copy of this report and letter will be sent to the NWT Water Board along with the recommendation for closure.

If you have any questions or concerns please contact me at (867) 669-2442.

Thank you,

Tim Morton  
Resource Management Officer (Inspector)  
Resource and Land Division  
Aboriginal Affairs and Northern Development Canada

cc. NWT Water Board – via email





## WATER LICENCE ENVIRONMENTAL INSPECTION REPORT

<b>Licensee:</b>	AANDC – CARD	Inspection Date – July 10 <sup>th</sup> 2015
------------------	--------------	--

<b>Water Licence No.</b>	N7L1-1814 & N7L1-1824	<b>Last Previous Inspection:</b>	August 30 <sup>th</sup> 2013
<b>Quantity of water not to be exceeded:</b>	N7L1-1814 – 100 Cubic Meters N7L1-1824 – 20 Cubic Meters	<b>Licence Expiry Date:</b>	N7L1-1814 – July 9 <sup>th</sup> 2009 N7L1-1824 – May 31 <sup>st</sup> 2013
<b>Contractor:</b>	N/A	<b>Subcontractor:</b>	N/A

<b>Location(s) Inspected:</b>	Johnson Point, Banks Island, NT
-------------------------------	---------------------------------

<b>Current Stage of Operation:</b>	Completed
------------------------------------	-----------

<b>Program Modifications Approved:</b>	N/A
--	-----

Compliance with Items: "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable

Part	Licence Items	Compliance with Items	Item # and Comments
A	Scope	A	
B	General Conditions	A	
C	Conditions Applying to Water Use	A	
D	Conditions Applying to Waste Disposal	A	
E	Conditions Applying to Modifications	A	
F	Conditions Applying to Contingency Planning	A	
G	Conditions Applying to Abandonment and Restoration	A	



## ENVIRONMENTAL INSPECTION REPORT Pg. 2 (Continued)

Date: July 10 <sup>th</sup> 2015	Licence #: S03L1-001
----------------------------------	----------------------

Explanatory Remarks
---------------------

An inspection of the Johnson Point remediation project was completed by Resource Management Officer Tim Morton on July 10<sup>th</sup> 2015. This inspection was conducted to ensure compliance with the applicable terms and conditions of both water licences N7L1-1814 and N7L1-1824.

Former camp location, tank farm, and landfills all appear to be in good condition and no concerns were noted. There were minor amounts of metal debris showing in a few locations, however this debris did not appear to be a risk to the environment. All armoring of the landfills was in excellent condition (Photo #3) and only minimal erosion was observed (Photo #5) throughout the site.

There was no identified water use or waste disposal associated with either of the water licences and no equipment remained onsite. There was some small fuel caches located next to the airstrip belonging to various government and private sector entities (Photo #6).

As there were no concerns noted during the inspection and no identified water use or water disposal, the Inspector recommends closure of both water licences N7L1-1814 & N7L1-1824 to the NWT Water Board.

Completed off Site  
Representative's Signature

Tim Morton  
Inspector

  
Inspector's Signature



**Photo #1 – Overview of Landfill C**



**Photo #2 – Southeast view from Landfill C**



**Photo #3 – East view from Landfill C. Note the Airstrip in the background**



**Photo #4 – Overview of the NRCAN research camp located near the former 2012 camp area from Landfill C**



**Photo #5 – Overview of minor erosion occurring onsite**



**Photo #6 – Remaining Government and Private Sector fuel located near the airstrip**

