



Telephone: 867-777-8907

Fax: 867-777-2090

February 12, 2021

GNWT Infrastructure  
P.O. Box 1320  
5015-49 Street  
Yellowknife, NT X1A2L9

**Attention: Kamran Ata**

<b>File Number</b>	<b>N5L1-1843</b>
<b>Type of Operation</b>	<b>CLASS B - INDUSTRIAL</b>
<b>Location</b>	<b>Gunghi Creek</b>

Dear Kamran Ata,

An inspection of the above noted operation was conducted on February 09, 2021 by Resource Management Officer II Herbert Allen .

Enclosed is a copy of the INDUSTRIAL Water Use Inspection Report.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

Cc:

Norman Snowshoe, Superintendent, Environment and Natural Resources, Beaufort Delta  
Richard Binder, Inuvialuit Water Board

Bag Service 1, Inuvik, NT X0E 0T0



**«INSP\_TYPE» WATER USE INSPECTION REPORT**

<b>LICENCE #:</b>	<b>N5L1-1843</b>	<b>EXPIRY DATE:</b>	<b>January 31, 2025</b>
<b>LICENCEE:</b>	<b>GNWT Infrastructure</b>	<b>PREVIOUS INSPECTION:</b>	<b>January 18, 2021</b>
<b>COMPANY REP:</b>	<b>Kamran Ata</b>	<b>INSPECTION DATE:</b>	<b>February 09, 2021</b>

**WASTE DISPOSAL - SOLID WASTE**

Disposal Method		brought to a land fill in town					
Open Dump	N	Landfill	N	Burn & Landfill	N	Underground	N
Offsite Removal	N	Other					
Owner / Operator							

Indicate:    **A - Acceptable**        **U - Unacceptable**        **N/A - Not Applicable**    **N/I - Not Inspected**

Runoff Diversion	A	SNP Samples Collected	
------------------	---	-----------------------	--

**Solid Waste Comments:**

During the inspection on February 9, 2021 at the Gunghi Creek site there were no concerns observed by the inspector.

**FUEL STORAGE**

Indicate:    **A - Acceptable**        **U - Unacceptable**        **N/A - Not Applicable**    **N/I - Not Inspected**

Owner:	GNWT Infrastructure	Operator:	Allen's Services	Condition of tanks:	A
Berms & Liners	A	Water within Berm:		Evidence of Leaks:	

Drainage Pipes	N/A	Pump Station and Catchment Berm	A	Runoff Diversion	N/A
Pipeline Condition	N/A				

**Fuel Storage Comments:**

There is no issue with the fuel storage at the time of the inspection, there was a large drip trays at the fueling station.



**«INSP\_TYPE» WATER USE INSPECTION REPORT**

**GENERAL CONDITIONS/REPORTS/PLANS**

Indicate:     **A - Acceptable**     **U - Unacceptable**     **N/A - Not Applicable**     **N/I - Not Inspected**

C &R Plan	A	Records & Reporting	A	Final Report	N/A
Geotechnical Inspection	A	Posting, Signage	A	Contingency Plan	A
Restorations Activities	A	Spills	A	O&M Plan	A
Maintenance	A	Modifications	A	Annual Report	N/A

**General Condition Comments:**

There is no concerns observed by the inspector along the creek bed where the work is being conducted. The area is clean and in good order and there is no water flowing or visible on the work site. There is no water being used for the project at this time until they are at the stage of mixing concrete. There is an access road to a lake at Km 120 that was made using a snow maker and is acceptable for use.

**ADDITIONAL COMMENTS/REMARKS**

Inspector's Signature: \_\_\_\_\_



# «INSP\_TYPE» WATER USE INSPECTION REPORT

## INSPECTION IMAGES

Figure 1



Figure 2





# «INSP\_TYPE» WATER USE INSPECTION REPORT

Figure 3



Figure 4





# «INSP\_TYPE» WATER USE INSPECTION REPORT

Figure 5



Figure 6





# «INSP\_TYPE» WATER USE INSPECTION REPORT

Figure 7



Figure 8

