



Mr. Michael Fabijan
Vice – President, Kavik - Stantec
P.O. Box 2400
Inuvik, NT X0E 0T0

November 5, 2021

Attention: Mr. Michael Fabijan

License Number: N7L1 - 1769
Type of Operation: CLASS B - INDUSTRIAL
Location: Mackenzie Delta

Dear **Mr. Michael Fabijan**,

An inspection of the above noted operation was conducted on October 7, 2021, by Water Resource Officer Lloyd Gruben. Enclosed is a copy of the Industrial Water Use Inspection Report.

Outstanding reports must be submitted to the Inuvialuit Water Board (Board) prior to recommendation of license closure. Please note there will be no return of the security deposit as the deposit has expired. Please see the attached report for details. It is the responsibility of Japex Canada Limited to ensure is in compliance with the conditions of Water License N7L1 – 1769 and any associated Acts and Regulations.

Please contact me at (867) 678 – 6652, if you have any questions, or concerns regarding the attached report.

Sincerely,

Lloyd Gruben
Water Resource Officer
Environment and Natural Resources
P.O. Box 2749
Inuvik, NT X0E 0T0
Ph: (867) 678 – 6652
Cell: (867) 678 – 0623

Cc:

Ernie Francis, A/Manager, Wildlife & Environment – Environment and Natural Resources
Mardy Semmler, Executive Director - Inuvialuit Water Board
Bijaya Adhikari, Science and Regulatory Coordinator – Inuvialuit Water Board
Rick Walbourne, Manager Water Regulatory – Environment and Natural Resources
Wendy Bidwell, Senior Water Resource Officer - Environment and Natural Resources



INDUSTRIAL WATER USE INSPECTION REPORT

LICENCE #:	N7L1 - 1769	EXPIRY DATE:	March 30, 2002
LICENCEE:	Japex Canada Ltd.	PREVIOUS INSPECTION:	July 21, 2020
COMPANY REP:	Mr. Michael Fabijan	INSPECTION DATE:	October 7, 2021

GENERAL CONDITIONS/REPORTS/PLANS

Indicate: **A - Acceptable** **U - Unacceptable** **N/A - Not Applicable** **N/I - Not Inspected**

C &R Plan	A	Records & Reporting	A	Final Report	U
Geotechnical Inspection	A	Posting, Signage	A	Contingency Plan	N/A
Restorations Activities	A	Spills	A	O&M Plan	N/A
Maintenance	A	Modifications	A	Annual Report	U

General Condition Comments:

- No annual reports have been submitted to the Inuvialuit Water Board since 2001 – 2002.
- Final report for sump re-assesment must be submitted to the Board as well.

ADDITIONAL COMMENTS/REMARKS

- Water License Number: N7L1 – 1769 is expired.
- Site clean-up and reclamation appears satisfactory.

MATTERS FOR FOLLOW UP

- Please submit the above noted outstanding reports to the Board.
- Once a report is submitted to the Inuvialuit Water Board relating to Part B, General Conditions: Item 1, c: details of work done, 1,d: details on the restoration of any sumps, and 1.f results from monitoring programs, this Water License N7L1 – 1769 may be closed.

NON-COMPLIANCE/VIOLATIONS OF ACT OR LICENCE

- No annual reports submitted to the Inuvialuit Water Board as per Water License N7L1 – 1769, Part B: General Conditions, Item 1.c, d and f.
- Item 1.c states: details of work completed,
- Item 1.d states: details on the restoration of any sumps,
- Item 1.f states: results from monitoring programs.

Inspector's Signature: _____





INDUSTRIAL WATER USE INSPECTION REPORT

INSPECTION IMAGES



Figure 1: Mallik Site



Figure 2: Mallik Site